


**State of New Jersey**  
**NOTIFICATION OF ASBESTOS ABATEMENT**  
(Pursuant to NJAC 8:60 and 12:120)

2016.0113.44576

Date of Notification (1) 01/11/2016		Name of Building Owner/Operator (2) JFK Boulevard Realty LLC							
Agencies Notified	Type Notification	Street Address							
<input checked="" type="checkbox"/> EPA <input checked="" type="checkbox"/> DEP <input checked="" type="checkbox"/> DOL  <input checked="" type="checkbox"/> DOH <input type="checkbox"/> DCA	<input type="checkbox"/> Initial <input checked="" type="checkbox"/> Amended Amendment # 1 <input type="checkbox"/> Emergency (including justification) <input type="checkbox"/> Cancellation	110 West 34th Street, 9th Floor							
		City, State, Zip Code New York, NY 10001							
		Name of Contact Henry Poyker	Telephone Number (212) 239-8580						
<b>FACILITY INFORMATION</b>									
Name of Facility Where Abatement is Taking Place (3)		Type of Facility (4)							
Street Address 2853 Kennedy Boulevard		<input checked="" type="checkbox"/> School (K-12) <input type="checkbox"/> Subchapter 8 (Other than K-12) <input type="checkbox"/> Other (i.e. private & commercial buildings, homes, etc.)							
City (5) Jersey City		Square Feet 55,150	# of Floors 6						
County (6) Hudson		County Code (7) (STATE USE ONLY)	Bldg. Age 188						
Name of Monitoring Firm Hired by Building Owner (8) Bio-Terra Solutions		ASCM No.	Name of Abatement Contractor (9) Incinia Contracting, Inc.						
Street Address 1130 West Chestnut Street		Street Address 1360 Clifton Avenue, Unit 365							
City, State, Zip Code Union, NJ 07083		City, State, Zip Code Clifton, NJ 07012							
Project Manager for Monitoring Firm Rick Eustaquio		Telephone No. (973) 494-3762	License No. 01036						
Start Date (10) 01/18/2016	Scheduled Completion Date (11) 02/29/2016	Name of OSHA Monitor Incinia Contracting, Inc.							
Occupancy Status During Abatement (Check Only One)		Street Address 1360 Clifton Avenue, Unit 365							
<input checked="" type="checkbox"/> Facility Closed/Vacated During Entire Period of Abatement <input type="checkbox"/> Abatement Performed Outside of Normal Facility Hours <input type="checkbox"/> Other - Describe: _____		City, State, Zip Code Clifton, NJ 07012							
Scope of Work (Check All That Apply)									
<input type="checkbox"/> ≥ 3 sf or ≥ 3 lf <input checked="" type="checkbox"/> ≥ 160 sf or ≥ 260 lf		<input checked="" type="checkbox"/> Renovation <input type="checkbox"/> Demolition							
		<input checked="" type="checkbox"/> Full Containment with Negative Pressure <input checked="" type="checkbox"/> Mini-Enclosure <input checked="" type="checkbox"/> Glovebag Procedure <input checked="" type="checkbox"/> Non-Exempted (*) and Non-Friable Procedure							
Location of Asbestos-Containing Material (ACM) <u>TO BE ABATED</u> In Facility (13)	Is Location Normally Used Solely by Maintenance/Custodial Staff? (12)			Description of Asbestos Containing Material (ACM) (i.e. thermal systems insulation, surfacing, VAT, or other miscellaneous)	Amount (Specify SF or LF)	Abatement Type			
	Yes	No	N/A			Removal	Repair	Encapsulate	Enclosure
6th Floor		X		VAT / Mastic	7,440 SF	X			
6th Floor		X		Pipe Insulation	228 LF	X			
5th Floor		X		VAT	7,000 SF	X			
5th Floor		X		Pipe Insulation	228 LF	X			
Name of Registered Waste Hauler Atlantic Carting/JR Contracting		NJDEP Waste Hauler ID No. NJ-641/JA-464	Cubic Yards of Waste 40	Name of Registered Landfill Grand Central Sanitary Landfill					
City, State Wayne, NJ			Disposal Date TBD	City, State Pen Argyl, PA					
Completed by Milena Zoric		Title Executive Director	Signature 	Date 01/11/2016					

Location of Asbestos-Containing Material (ACM) <u>TO BE ABATED</u> In Facility (13)	Is Location Normally Used Solely by Maintenance Custodial Staff? (12)			Description of Asbestos Containing Material (ACM) (i.e. thermal systems insulation, surfacing, VAT, or other miscellaneous)	Amount (Specify SF or LF)	Abatement Type			
	Yes	No	N/A			Removal	Repair	Encapsulate	Enclosure
4 <sup>th</sup> Floor		X		VAT	7,440 SF	X			
4 <sup>th</sup> Floor		X		Pipe Insulation	595 LF	X			
3 <sup>rd</sup> Floor		X		VAT	738 SF	X			
3 <sup>rd</sup> Floor		X		Pipe Insulation	430 LF	X			
2 <sup>nd</sup> Floor		X		VAT	240 SF	X			
2 <sup>nd</sup> Floor		X		Pipe Insulation	595 LF	X			
Basement		X		VAT	5,455 SF	X			
Basement		X		Pipe Insulation	270 LF	X			
Boiler Room		X		Boiler Jacket Insulation	250 SF	X			
Boiler Room		X		Boiler Breaching Insulation	300 SF	X			